



Service Bulletin

No. : MZ02-021

Date: December 4, 2006

Model: SR6200/SR7200

Subject: No sound in CS5.1 mode with a 32kHz PCM input

Symptom: No sound in CS5.1 mode with a 32kHz PCM input.

Solution: Replace the EPROM (IC707) with the new version.

Parts:

Ref#	Description	Part Number
IC707	EPROM	*HC107300R

Serial Number Range:

Model # Serial #
SR6200/U1B: MZ030212000001 and after.
SR7200/U1B: MZ020208001558 and after.

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.